

Sensors installed January 2001 and were doing a tremendous job reducing KW and kWh.
 Please review the Bar Chart 10 Year History. All information was from Utility Programs.
 May 28, 2001 Rolling blackout caused the chiller to be reset to default causing it to run more often.
 Please scroll down and witness June 2001 and then July 2001 when program was re-installed.



